

- ← MIXING AND DRYING
- ← ADD AT LEAST ONE OF THE COMPOUNDS SELECTED FROM AMONG ALKALINE EARTH METAL OXIDES AND COMPOUNDS THAT CHANGE INTO ALKALINE EARTH METAL OXIDES WHEN FIRED
- ← PRIMARY FIRING AT A TEMPERATURE FROM 1150 TO 1350 °C
- ← ADD HALIDE
- ← WASHING
- ← GRINDING
- ← WASHING, FILTRATING, AND DRYING
- ← SECONDARY FIRING AT A TEMPERATURE FROM 600 TO 1000 °C
- ← WASHING
- ← ETCHING
- ← WASHING
- ← DRYING
- ← SIEVING

PHOSPHOR [ZnS · aAO(A=Mg, Ca, Sr, Ba、 $0.001 \leq a \leq 0.01$)]

FIG. 1




FIG. 2